

Schneider APC UPS's

UPS System (External Battery Cabinet)

0	0
710010	UPS w/ APC Secure UPS 1300VA/1300 W 120 VAC In/Out RM Plus Bypass Unit with 12' Harness (No Cabinet or Power Panel)
710011	Complete UPS w/ APC Secure UPS 1300VA/1300 W 120 VAC In/Out RM Plus Bypass Unit with 12' Harness (NO Cabinet or Power Panel but with Generator Option)
APC-TXDOT	Turnkey UPS w/ APC Secure UPS 1300VA/1300 W 120 VAC In/Out RM, Bypass Unit, 12' Harness, RTC Cabinet and Power Panel 4 MK 110 AH Batteries (No Generator Plug)
APC-DOT	Turnkey UPS w/ APC Secure UPS 1300VA/1300 W 120 VAC In/Out RM Plus Bypass Unit, 12' Harness, RTC Cabinet and Power Panel 4 MK 110 AH Batteries and Generator Plug
710001	APC Secure UPS 1300VA/1300 W 120 VAC In/Out RM Conformal Coated
710002	APC Schneider SecureUPS Bypass Unit W/ Generator input, W/O Batteries
710002NOGEN	APC Schneider SecureUPS Bypass Unit W/O Generator input, W/O Batteries
710003	APC Schneider Battery Harness 12'
47-HAR4	APC Schneider Battery Harness 4'
03-UPSGEN	Generator Option (Incl. Automatic Switch, Dead Face Panel, 30A Generator Receptacle, Wiring)
13-8A30 HEI	MK 110 Amp 12V Batteries
710006	APC 100 Amp 12V Batteries
710009	Set of 4 APC 100 Amp 48V Batteries
260012	Aluminum Mounting Cabinet
PNS10 -03-UPSCTC	Power Panel, wiring and Labor
PNS10 -03-UPSFANTHERM	Add ,Thermostat and Fan Only (NO POWER PANEL)
PNS10 -03-UPSCONF	Add Confirmation Light
PNS10 -03-UPSDOOR	Add Door Switch